



ASSOCIATION CONNECTING  
ELECTRONICS INDUSTRIES®



IPC/WHMA-A-620A

# Requirements and Acceptance for Cable and Wire Harness Assemblies

Developed by the IPC Task Group (7-31f) of the Product Assurance Subcommittee (7-30) and the WHMA Industry Technical Guidelines Committee (ITGC)

**Supersedes:**  
IPC/WHMA-A-620 -  
January 2002

Users of this publication are encouraged to participate in the development of future revisions.

Contact:

IPC  
3000 Lakeside Drive, Suite 309S  
Bannockburn, Illinois  
60015-1219  
Tel 847 615.7100  
Fax 847 615.7105

Wiring Harness Manufacturers Assoc.  
7500 Flying Cloud Drive, Suite 900  
Eden Prairie, Minnesota  
55344  
Tel 952 835.4180  
Fax 952 835.4774

# Table of Contents

<b>1 Requirements and Acceptance for Cable and Wire Harness Assemblies</b> .....	1-1	<b>2 Applicable Documents</b> .....	2-1
1.1 Scope .....	1-1	2.1 IPC .....	2-1
1.2 Purpose .....	1-1	2.2 Joint Industry Standards .....	2-1
1.3 Approach to This Document .....	1-1	2.3 Society of Automotive Engineers (SAE) .....	2-1
1.4 Shall or Should .....	1-1	2.4 American National Standards Institute (ANSI) .....	2-2
1.5 Uncommon or Specialized Designs .....	1-1	2.5 International Organization for Standardization (ISO) .....	2-2
1.6 Terms and Definitions .....	1-1	2.6 ESD Association (ESDA) .....	2-2
1.7 Classes of Products .....	1-2	<b>3 Preparation</b> .....	3-1
1.8 Document Hierarchy .....	1-2	3.1 Stripping .....	3-2
1.9 Tool and Equipment Control .....	1-2	3.2 Strand Damage and End Cuts .....	3-2
1.10 Observable Criteria .....	1-3	3.3 Conductor Deformation/Birdcaging .....	3-5
1.11 Defects and Process Indicators .....	1-3	3.4 Twisting of Wires .....	3-7
1.12 Inspection Conditions .....	1-3	3.5 Wire Insulation Damage .....	3-8
1.12.1 Target .....	1-3	<b>4 Soldered Terminations</b> .....	4-1
1.12.2 Acceptable .....	1-3	4.1 Material, Components and Equipment .....	4-2
1.12.3 Process Indicator .....	1-3	4.1.1 Materials .....	4-2
1.12.4 Defect .....	1-3	4.1.1.1 Solder .....	4-2
1.12.5 Disposition .....	1-3	4.1.1.2 Flux .....	4-2
1.12.6 Product Classification Implied Relationships .....	1-3	4.1.1.3 Adhesives .....	4-3
1.12.7 Conditions Not Specified .....	1-3	4.1.1.4 Solderability .....	4-3
1.13 Electrical Clearance .....	1-3	4.1.1.5 Tools and Equipment .....	4-3
1.14 Measurement Units and Applications .....	1-4	4.1.2 Gold Removal .....	4-3
1.15 Verification of Dimensions .....	1-4	4.2 Cleanliness .....	4-4
1.16 Visual Inspection .....	1-4	4.2.1 Presoldering .....	4-4
1.16.1 Lighting .....	1-4	4.2.2 Postsoldering .....	4-4
1.16.2 Magnification Aids and Lighting .....	1-4	4.2.2.1 Particulate Matter .....	4-4
1.17 Electrostatic Discharge (ESD) Protection .....	1-5	4.2.2.2 Flux Residue .....	4-5
1.18 Contamination .....	1-5	4.2.2.2.1 Cleanable Flux .....	4-5
1.19 Materials and Processes .....	1-5	4.2.2.2.2 No-Clean Process .....	4-5
		4.3 Solder Connection .....	4-6
		4.3.1 General Requirements .....	4-7
		4.3.2 Soldering Anomalies .....	4-8
		4.3.2.1 Exposed Basis Metal .....	4-8
		4.3.2.2 Exposed Surface Finishes .....	4-8
		4.3.2.3 Partially Visible or Hidden Solder Connections .....	4-8

## Table of Contents (cont.)

<b>4.4 Wire/Lead Preparation, Tinning</b> .....	4-9	<b>5.4 Termination Ferrule Crimp</b> .....	5-29
<b>4.5 Wire Insulation</b> .....	4-11	<b>6 Insulation Displacement Connection (IDC)</b> .....	6-1
4.5.1 Clearance .....	4-11	<b>6.1 Mass Termination, Flat Cable</b> .....	6-2
4.5.2 Postsolder Damage .....	4-13	6.1.1 End Cutting .....	6-2
<b>4.6 Insulation Sleeveing</b> .....	4-14	6.1.2 Notching .....	6-3
<b>4.7 Birdcaged Wire (Soldered)</b> .....	4-16	6.1.3 Planar Ground Plane Removal .....	6-4
<b>4.8 Connection Requirements</b> .....	4-17	6.1.4 Connector Position .....	6-5
4.8.1 Turret Terminals .....	4-19	6.1.5 Connector Skew & Lateral Position .....	6-8
4.8.2 Bifurcated Terminals .....	4-21	6.1.6 Retention .....	6-9
4.8.2.1 Side Route Attachments .....	4-21	<b>6.2 Discrete Wire Termination</b> .....	6-10
4.8.2.2 Bottom and Top Route Attachments .....	4-23	6.2.1 General .....	6-10
4.8.2.3 Staked Wires .....	4-24	6.2.2 Position of Wire .....	6-11
4.8.3 Slotted Terminals .....	4-25	6.2.3 Overhang (Extension) .....	6-12
4.8.4 Pierced/Perforated/Punched Terminals .....	4-26	6.2.4 Wire Holder .....	6-13
4.8.5 Hook Terminals .....	4-27	6.2.5 Damage in Connection Area .....	6-15
4.8.6 Cup Terminals .....	4-29	6.2.6 End Connectors .....	6-16
4.8.7 Series Connected Terminals .....	4-30	6.2.7 Wiremount Connectors .....	6-18
4.8.8 Lead/Wire Placement - AWG 30 and Smaller Diameter Wires .....	4-31	6.2.8 Subminiature D-Connector (Series Bus Connector) .....	6-19
<b>4.9 Solder Connection</b> .....	4-32	6.2.9 Modular Connectors (RJ Type) .....	6-21
4.9.1 Turret Terminals .....	4-34	<b>7 Ultrasonic Welding</b> .....	7-1
4.9.2 Bifurcated Terminals .....	4-35	<b>7.1 Insulation Clearance</b> .....	7-2
4.9.3 Slotted Terminals .....	4-37	<b>7.2 Weld Nugget</b> .....	7-3
4.9.4 Pierced/Perforated Terminals .....	4-38	<b>8 Splices</b> .....	8-1
4.9.5 Hook Terminals .....	4-39	<b>8.1 Soldered Splices</b> .....	8-2
4.9.6 Cup Terminals .....	4-40	8.1.1 Mesh .....	8-2
<b>5 Crimp Terminations (Contacts and Lugs)</b> .....	5-1	8.1.2 Wrap .....	8-4
<b>5.1 Stamped and Formed - Open Barrel</b> .....	5-2	8.1.3 Hook .....	8-5
5.1.1 Insulation Support Crimp .....	5-3	8.1.4 Lap .....	8-6
5.1.2 Insulation Inspection Window .....	5-5	8.1.4.1 Two or More Conductors .....	8-7
5.1.3 Conductor Crimp .....	5-7	8.1.4.2 Insulation Opening (Window) .....	8-9
5.1.4 Crimp Bellmouth .....	5-9	8.1.5 Heat Shrinkable Solder Devices .....	8-11
5.1.5 Conductor Brush .....	5-11	<b>8.2 Crimped Splices</b> .....	8-13
5.1.6 Stamped and Formed Carrier Cutoff Tab .....	5-13	8.2.1 Barrel .....	8-13
<b>5.2 Stamped and Formed - Closed Barrel</b> .....	5-14	8.2.2 Double Sided .....	8-16
5.2.1 Insulation Support Crimp .....	5-15	<b>8.3 Ultrasonic Weld Splices</b> .....	8-20
5.2.2 Conductor Crimp and Bellmouth .....	5-17	<b>9 Connectorization</b> .....	9-1
<b>5.3 Machined Contacts</b> .....	5-19	<b>9.1 Hardware Mounting</b> .....	9-2
5.3.1 Insulation Clearance .....	5-19	9.1.1 Jackpost - Height .....	9-2
5.3.2 Insulation Support Style .....	5-22	9.1.2 Jackscrews - Protrusion .....	9-3
5.3.3 Conductor Location .....	5-23		
5.3.4 Crimping .....	5-25		
5.3.5 CMA Buildup .....	5-27		

## Table of Contents (cont.)

<b>9.2 Strain Relief</b> .....	9-4	<b>11.2 Wire Measuring</b> .....	11-5
9.2.1 Clamp Fit .....	9-4	11.2.1 Electrical Terminal Reference Location .....	11-5
9.2.2 Wire Dress .....	9-5	11.2.2 Length .....	11-6
9.2.2.1 Straight Approach .....	9-6	<b>12 Marking/Labeling</b> .....	12-1
9.2.2.2 Side Approach .....	9-7	<b>12.1 Content</b> .....	12-2
<b>9.3 Sleeving and Boots</b> .....	9-8	<b>12.2 Legibility</b> .....	12-2
9.3.1 Position .....	9-8	<b>12.3 Permanency</b> .....	12-4
9.3.2 Bonding .....	9-9	<b>12.4 Location and Orientation</b> .....	12-4
<b>9.4 Connector Damage</b> .....	9-12	<b>12.5 Functionality</b> .....	12-6
9.4.1 Criteria .....	9-12	<b>12.6 Marker Sleeve</b> .....	12-7
9.4.2 Limits - Hard Face - Mating Surface .....	9-13	12.6.1 Wrap Around .....	12-7
9.4.3 Limits - Soft Face - Mating Surface or Rear Seal Area .....	9-14	12.6.2 Tubular .....	12-9
9.4.4 Contacts .....	9-15	<b>12.7 Flag Markers</b> .....	12-10
<b>9.5 Installation of Contacts and Sealing Plugs into Connectors</b> .....	9-16	12.7.1 Adhesive .....	12-10
9.5.1 Installation of Contacts .....	9-16	12.7.2 Tie Wrap .....	12-10
9.5.2 Installation of Sealing Plugs .....	9-18	<b>13 Coaxial and Twinaxial Cable Assemblies</b> .....	13-1
<b>10 Molding/Potting</b> .....	10-1	<b>13.1 Stripping</b> .....	13-2
<b>10.1 Molding</b> .....	10-2	<b>13.2 Center Conductor Termination</b> .....	13-4
10.1.1 Mold Fill - Initial .....	10-2	13.2.1 Crimp .....	13-4
10.1.2 Mold Fill - Final .....	10-4	13.2.2 Solder .....	13-6
10.1.3 Mismatch .....	10-8	<b>13.3 Solder Ferrule Pins</b> .....	13-8
10.1.4 Blow Through .....	10-9	13.3.1 General .....	13-8
10.1.5 Terminal/Contact Position .....	10-10	13.3.2 Insulation .....	13-10
10.1.6 Fit .....	10-12	<b>13.4 Coaxial Connector - Printed Wire Board Mount</b> .....	13-11
10.1.7 Flashing .....	10-14	<b>13.5 Coaxial Connector - Center Conductor Length - Right Angle Connector</b> .....	13-12
10.1.8 Cracks, Flow Lines, Chill Marks (Knit Lines) or Weld Lines .....	10-16	<b>13.6 Coaxial Connector - Center Conductor Solder</b> .....	13-14
10.1.9 Color .....	10-18	<b>13.7 Coaxial Connector - Terminal Cover</b> .....	13-16
10.1.10 Wire Insulation, Jacket or Sleeving Damage .	10-18	13.7.1 Soldering .....	13-16
10.1.11 Curing .....	10-20	13.7.2 Press Fit .....	13-17
10.1.12 Rework .....	10-21	<b>13.8 Shield Termination</b> .....	13-18
<b>10.2 Potting</b> .....	10-22	13.8.1 Clamped Ground Rings .....	13-18
10.2.1 Filling .....	10-22	13.8.2 Crimped Ferrule .....	13-19
10.2.2 Fit to Wire or Cable .....	10-23		
10.2.3 Curing .....	10-24		
<b>11 Cable Assemblies and Wires</b> .....	11-1		
<b>11.1 Cable Measuring</b> .....	11-2		
11.1.1 Reference Surfaces .....	11-2		
11.1.1.1 Straight/Axial Connectors .....	11-2		
11.1.1.2 Right-Angle Connectors .....	11-2		
11.1.2 Length .....	11-3		
11.1.3 Breakout .....	11-4		

## Table of Contents (cont.)

<b>13.9 Center Pin Position</b> .....	13-21	<b>15.3 Shield Termination - Connector</b> .....	15-15
<b>13.10 Semirigid Coax</b> .....	13-22	15.3.1 Shrink and Crimp .....	15-15
13.10.1 Bending and Deformation .....	13-22	15.3.2 Shield Jumper Wire Attachment .....	15-19
13.10.2 Surface Condition .....	13-25	<b>15.4 Shield Termination - Splicing</b> .....	15-20
13.10.3 Dielectric Cutoff .....	13-27	15.4.1 Solder .....	15-20
13.10.4 Dielectric Cleanliness .....	13-29	15.4.2 Tie/Tape On .....	15-22
13.10.5 Solder .....	13-30	<b>15.5 Tapes - Barrier and Conductive, Adhesive or Nonadhesive</b> .....	15-23
<b>13.11 Swage-Type Connector</b> .....	13-32	<b>15.6 Conduit (Shielding)</b> .....	15-24
<b>13.12 Soldering and Stripping of Biaxial Wire</b> .....	13-33	<b>15.7 Shrink Tubing - Conductive Lined</b> .....	15-25
13.12.1 Jacket and Tip Installation .....	13-33	<b>16 Cable/Wire Harness Protective Coverings</b> .....	16-1
13.12.2 Ring Installation .....	13-35	<b>16.1 Braid</b> .....	16-2
<b>14 Securing</b> .....	14-1	16.1.1 Direct Applied .....	16-2
<b>14.1 Tie Wrap/Lacing Application</b> .....	14-2	16.1.2 Prewoven .....	16-4
14.1.1 Tightness .....	14-6	<b>16.2 Sleeving/Shrink Tubing</b> .....	16-6
14.1.2 Damage .....	14-7	<b>16.3 Spiral Plastic Wrap (Spiral Wrap Sleeving)</b> .....	16-7
14.1.3 Spacing .....	14-8	<b>16.4 Conduit (Containment Loom)</b> .....	16-8
<b>14.2 Breakouts</b> .....	14-9	<b>16.5 Tapes, Adhesive and Nonadhesive</b> .....	16-9
14.2.1 Individual Wires .....	14-9	<b>17 Finished Assembly Installation</b> .....	17-1
14.2.2 Spacing .....	14-10	<b>17.1 General</b> .....	17-2
<b>14.3 Routing</b> .....	14-13	<b>17.2 Hardware Installation</b> .....	17-3
14.3.1 Wire Crossover .....	14-13	17.2.1 Threaded Fasteners .....	17-3
14.3.2 Bend Radius .....	14-14	17.2.2 Minimum Torque for Electrical Connections .....	17-6
14.3.3 Coaxial Cable .....	14-15	17.2.3 Wires .....	17-7
14.3.4 Unused Wire Termination .....	14-16	17.2.4 High Voltage Applications .....	17-10
14.3.5 Ties over Splices and Ferrules .....	14-17	<b>17.3 Wire/Harness Installation</b> .....	17-11
<b>15 Harness/Cable Electrical Shielding</b> .....	15-1	17.3.1 Stress Relief .....	17-11
<b>15.1 Braided</b> .....	15-2	17.3.2 Wire Dress .....	17-12
15.1.1 Direct Applied .....	15-3	17.3.3 Service Loops .....	17-13
15.1.2 Prewoven .....	15-5	<b>18 Solderless Wrap</b> .....	18-1
<b>15.2 Shield Termination</b> .....	15-6	<b>18.1 Number of Turns</b> .....	18-2
15.2.1 Shield Jumper Wire .....	15-6	<b>18.2 Turn Spacing</b> .....	18-3
15.2.1.1 Attached Lead .....	15-6	<b>18.3 End Tails, Insulation Wrap</b> .....	18-4
15.2.1.1.1 Solder/Heat Shrinkable Solder Device .....	15-7		
15.2.1.1.2 Crimp .....	15-11		
15.2.1.2 Shield Braid .....	15-11		
15.2.1.2.1 Woven .....	15-11		
15.2.1.2.2 Combed and Twisted .....	15-12		
15.2.1.3 Daisy Chain .....	15-12		
15.2.2 No Shield Wire .....	15-13		

## Table of Contents (cont.)

<b>18.4 Raised Turns Overlap</b> .....	18-6	<b>19.6 Mechanical Tests</b> .....	19-10
<b>18.5 Connection Position</b> .....	18-7	19.6.1 Selection .....	19-10
<b>18.6 Wire Dress</b> .....	18-9	<b>19.7 Mechanical Test Methods</b> .....	19-11
<b>18.7 Wire Slack</b> .....	18-10	19.7.1 Crimp Height (Dimensional Analysis) .....	19-11
<b>18.8 Plating</b> .....	18-11	19.7.1.1 Terminal Positioning .....	19-12
<b>18.9 Damage</b> .....	18-12	19.7.2 Pull Force (Tensile) .....	19-13
18.9.1 Insulation .....	18-12	19.7.2.1 Without Documented Process Control .....	19-14
18.9.2 Wires and Terminals .....	18-13	19.7.3 Crimp Force Monitoring .....	19-16
<b>19 Testing</b> .....	19-1	19.7.4 Crimp Tool Qualification .....	19-16
<b>19.1 Nondestructive Tests</b> .....	19-2	19.7.5 Contact Retention Verification .....	19-16
<b>19.2 Testing After Rework or Repair</b> .....	19-2	19.7.6 Coaxial Shield Pull Force (Tensile) .....	19-17
<b>19.3 Intended Table Usage</b> .....	19-2	19.7.7 RF Connector Shield Ferrule Torsion .....	19-18
<b>19.4 Electrical Test</b> .....	19-3	19.7.8 User Defined .....	19-18
19.4.1 Selection .....	19-3	<b>Appendix A Terms and Definitions</b> .....	A-1
<b>19.5 Electrical Test Methods</b> .....	19-4	<b>Appendix B Metric Conversion Table</b> .....	B-1
19.5.1 Continuity .....	19-4	<b>Appendix C Reproducible Test Tables</b> .....	C-1
19.5.2 Shorts .....	19-5	<b>Standard Improvement Form</b>	
19.5.3 Dielectric Withstanding Voltage (DWV) .....	19-6		
19.5.4 Insulation Resistance (IR) .....	19-7		
19.5.5 Voltage Standing Wave Ratio (VSWR) .....	19-8		
19.5.6 Insertion Loss .....	19-8		
19.5.7 Reflection Coefficient .....	19-9		
19.5.8 User Defined .....	19-9		

Foreword

If a conflict occurs between the English and translated versions of this document, the English version will take precedence.

1.1 Scope This standard is a collection of visual, electrical and mechanical quality acceptability requirements for Cable, Wire and Harness Assemblies. It was prepared by the Industry Technical Guidelines Committee of the Wire Harness Manufacturers Association and the Product Assurance Committee of IPC - Association Connecting Electronic Industries. IPC/WHMA-A-620 can be used as a stand-alone document for purchasing products; however it does not specify frequency of in-process inspection or frequency of end product inspection. No limit is placed on the number of process indicators or the number of allowable repair/rework of defects. Such information should be developed with a statistical process control plan (see IPC-9191).

1.2 Purpose This publication describes tests and acceptability criteria for producing crimped, mechanically secured, or soldered interconnections and the associated lacing/restraining criteria associated with cable and harness assemblies. Any method that produces an assembly conforming to the acceptability requirements described in this standard may be used.

1.3 Approach to This Document The illustrations in this document portray specific points noted in the title of each section. A brief description follows each illustration. The development committee recognizes that different parts of the industry have different definitions for some terms used herein. For the purposes of this document, the terms cable and wire harness are used interchangeably.

Class 3 shall<sup>1</sup> develop and implement a documented process control system. A documented process control system, if established, shall<sup>2</sup> define process control and corrective action limits. This may or may not be a "statistical process control" system. The use of "statistical process control" (SPC) is optional and should be based on factors such as design stability, lot size, production quantities, and the needs of the company.

Process control methodologies shall<sup>2</sup> be used in the planning, implementation and evaluation of the manufacturing processes used to produce cables and wire harness assemblies. The philosophy, implementation strategies, tools and techniques may be applied in differ-

- (1) Class 1-Not Est
Class 2-Not Est
Class 3-Defect
(2) Class 1-Not Est
Class 2-Defect
Class 3-Defect

ent sequences depending on the specific company, operation, or variable under consideration to relate process control and capability to end product requirements.

1.4 Shall or Should The word "shall" is used in the text of this document wherever a requirement is mandatory.

Where the word "shall" leads to a hardware defect for at least one class, the requirements for each class are annotated in text boxes located adjacent to that occurrence in the text. When this standard doesn't provide acceptance criteria for a specific class, the text box will note "Not Est" for that class (see 1.5).

The word "should" reflects recommendations and is used to reflect general industry practices and procedures for guidance only.

1.5 Uncommon or Specialized Designs IPC/WHMA-A-620, as an industry consensus document, cannot address all of the possible product design combinations. However, the standard does provide criteria for commonly used technologies. Where uncommon or specialized technologies are used, it may be necessary to develop unique acceptance criteria. The development of unique criteria should include user involvement or consent and the criteria developed should include an agreed upon definition for acceptance of each characteristic.

Whenever possible, new criteria or criteria on specialized products should be submitted, using the Standard Improvement Form included in this standard, to the IPC Technical Committee to be considered for inclusion in upcoming revisions of this standard.

1.6 Terms and Definitions Terms are consistent with the definitions provided by IPC-T-50. For the understanding of this document, selected definitions pertaining specifically to cable and wire harness manufacturing are listed below and in Appendix A.

Manufacturer (Assembler) - The individual, organization, or company responsible for the assembly process and verification operations necessary to ensure full compliance of assemblies to this standard.

Objective Evidence - Documentation in the form of hard copy, computer data, video, or other media.

Process Control - A system or method to continually steer an operation in reducing variation in the processes or products to meet or exceed the goal in quality and performance.

Supplier - The individual, organization or company which provides to the manufacturer (assembler) components (cables,